


**Figure 1**



2/45



**Figure 2**



3/45




Figure 3A





Figure 3B






6/45




**Figure 4B**



7/45



**Figure 4C**



**Figure 4D**





9/45

504


	00	01	10	11
11	$0.95 V_H$	$0.90 V_H$	$0.90 V_H$	0
10	$0.90 V_H$	$0.95 V_H$	0	$0.90 V_H$
01	$0.90 V_H$	0	$0.95 V_H$	$0.90 V_H$
00	0	$0.90 V_H$	$0.90 V_H$	$0.95 V_H$

502

**Figure 5**




10/45



**Figure 6**




11/45



**Figure 7A**



12/45



**Figure 7B**



13/45




Figure 7C



14/45




Figure 7D



15/45

	00	01	10	11	
11	$0.95 V_H$	$0.90 V_H$	$0.90 V_H$	0	802
10	$0.90 V_H$	$0.95 V_H$	0	$0.90 V_H$	
01	$0.90 V_H$	0	$0.90 V_H$	0	804
00	0	$0.90 V_H$	$0.90 V_H$	$0.95 V_H$	808

806

**Figure 8**




Figure 9





17/45

	00	01	10	11	
11	0.90 V <sub>H</sub>	0.90 V <sub>H</sub>	0	0	1002
1012	10	0.90 V <sub>H</sub>	0.95 V <sub>H</sub>	0	0.90 V <sub>H</sub> 1004
1006	01	0.90 V <sub>H</sub>	0	0.90 V <sub>H</sub>	0 1010
00	0	0.90 V <sub>H</sub>	0.90 V <sub>H</sub>	0.95 V <sub>H</sub>	1014

**Figure 10**





19/45





Figure 12A




20/45




**Figure 12B**



21/45



**Figure 12C**



**Figure 12D**



23/45

	00	01	10	11
11	$0.95 V_H$	$0.95 V_H$	$0.95 V_H$	0
10	$0.95 V_H$	$0.95 V_H$	0	$0.95 V_H$
01	$0.95 V_H$	0	$0.95 V_H$	$0.95 V_H$
00	0	$0.95 V_H$	$0.95 V_H$	$0.95 V_H$

**Figure 13**



24/45




Figure 14





25/45




Figure 15A



26/45





Figure 15B




27/45



### Figure 15C



28/45



**Figure 15D**



29/45

	00	01	10	11
11	$0.95 V_H$	$0.95 V_H$	$0.95 V_H$	0
10	$0.95 V_H$	$0.95 V_H$	0	$0.95 V_H$
01	$0.95 V_H$	0	$0.90 V_H$	$0.90 V_H$
00	0	$0.95 V_H$	$0.95 V_H$	$0.95 V_H$

1602

1604

**Figure 16**



30/45




Figure 17




31/45

	00	01	10	11
11	$0.90 V_H$	$0.95 V_H$	$0.90 V_H$	0
10	$0.95 V_H$	$0.95 V_H$	0	$0.95 V_H$
01	$0.95 V_H$	0	$0.90 V_H$	$0.90 V_H$
00	0	$0.95 V_H$	$0.95 V_H$	$0.95 V_H$

**Figure 18**



32/45



**Figure 19**





33/45

	00	01	10	11
11	$0.90 V_H$	$0.95 V_H$	$0.90 V_H$	0
10	$0.95 V_H$	$0.90 V_H$	0	$0.90 V_H$
01	$0.95 V_H$	0	$0.90 V_H$	$0.90 V_H$
00	0	$0.95 V_H$	$0.95 V_H$	$0.95 V_H$

**Figure 20**



34/45




Figure 21




35/45


	00	01	10	11
11	0	$0.90 V_H$	$0.90 V_H$	0
10	$0.95 V_H$	$0.90 V_H$	0	$0.90 V_H$
01	$0.95 V_H$	0	$0.90 V_H$	$0.90 V_H$
00	0	$0.95 V_H$	$0.95 V_H$	$0.95 V_H$

**Figure 22**






**Figure 23B**




**Figure 24A**




**Figure 24B**



39/45



**Figure 25**



**Figure 26A**







Figure 26B




42/45




**Figure 27**



43/45



**Figure 28**



**Figure 29A**



45/45




Figure 29B